

AUSTRALIAN FEDERATED UNION OF LOCOMOTIVE EMPLOYEES



Circular: 21/20
Ref: Black Mould NRG
20/02/2020

Black Mould in NGR Units

Dear members,

I'm aware that black mould has been found in some NGR units. Specialist hygiene and WHS personnel have inspected them and I've been advised by QR that there is no risk to Traincrew or the public.

TMR and Bombardier have giving me an undertaking to update me by COB Friday 21 February 2020 about the cause and process of addressing the issue.

If you NGR unit isn't safe to use report it to the yard master or control immediately.

I will keep you updated.

In Solidarity,

Michael McKitrick
State Secretary